

KCI-P Installation Instructions

1. Locate each KCI-P Isolator as specified on the Submittal Drawing.
2. Remove the Nut and Washer from the Adjustment Post.
3. Align the equipment and center the Isolator Housings on the Adjustment Post.
4. Mark the Isolator Housing attachment locations.
5. Raise the equipment and install the Isolator Housing attachment anchors or fasteners.
6. Lower the equipment and install the Nut and Washer on the Adjustment Post and tighten.
7. Adjust the KCI-P Isolator by turning the Leveling Nut 1 to 2 turns clockwise.
8. Repeat turning the Leveling Nut 1 to 2 turns clockwise on each isolator until the gap between the Isolator Housing and Rubber Snubber faces is equal on the top and bottom.
9. Do not move the KCI-P Isolators laterally with the weight of the equipment on them. Raise the equipment to remove the weight from the KCI-P Isolators before moving.

